

Chief, Intelligence Information Staff, ORR

7 May 1957

THRU : Chief, Industrial Division, ORR

Acting Chief, Electrical Equipment Branch, ORR

Request for Requirements, ORR 11536, A-10-985-401

The following requirements are submitted:

1. What is the size and composition of the labor force at the "Konverta" Factory?

25X6A 2. What is the size and composition of the production of the [REDACTED] Factory (in both value and physical units, if possible)? Is the full capacity of the plant being utilized? If not, how much?

3. What are the sources of raw materials for the plant? What is their quality? Any shortages? If so, how badly was production disrupted?

4. Who are the consumers of the plant's output? List domestic and foreign consumers and the approximate percentage of the output each consumes.

5. What is the quality of the plant's products compared to the products of other Hungarian plants and to similar products in other countries?

25X6A

6. Approximately what percentage of [REDACTED] total production of these types of products (selenium rectifier apparatus, battery charges, etc.) does this plant account for?

25X1A9a

25X1A9a

ORR/D/I/EE: [REDACTED] eem/3697 (7 May 57)